

Comparabile**Totale 29 punti | 79%****Totale 36 punti | 73%**

	RESTAZIONI 8.6 punti	Bambino di 18 mesi Seggiolino Britax Romer Baby Safe Gruppo 0, 0+ Posizione All'indietro Installazione Ancoraggi ISOFIX e intelaiatura supporto
	RESTAZIONI 10.2 punti ISTRUZIONI 4.0 punti INSTALLAZIONE 2.0 punti	Bambino di 3 anni Seggiolino Britax Romer Duo Plus Gruppo 1 Posizione In avanti Installazione Ancoraggi ISOFIX e punto d'aggancio

VALUTAZIONE BASATA SUL VEICOLO 5.0 punti[Vedi commenti](#)**Totale 21 punti | 58%**

	TESTA 15.1 punti BACINO 0.0 punti GAMBA 5.8 punti	DISPOSITIVI DI LIMITAZIONE VELOCITÀ 0.0 punti CONTROLLO ELETTRONICO DELLA STABILITÀ (ESC) 3.0 punti SISTEMA SBR conducente passeggero 0	Totale 5 punti 71%
--	---	---	-----------------------------

Color Key:
█ Buona
█ Adeguata
█ Marginale

Dettagli della vettura testata**Specifiche****Modello testato**

Subaru Legacy 2.0D, LHD

Tipo carrozzeria

5 porte Translation not found

Anno di pubblicazione

2009

Peso

1400

Numero di identificazione veicolo (VIN) a cui si riferisce la valutazione

Applicable a tutte le applies Legacies testate

Classe

LARGE FAMILY

Safety equipment

Pretensionatori della cintura di sicurezza sedile anteriore

Limitatori di carico cinture di sicurezza anteriori

Airbag anteriore conducente

a una fase

Airbag anteriore passeggero

a una fase

Airbag laterali

Airbag laterale per la testa

Commenti

Protezione dei adulti

The passenger compartment remained stable in the frontal impact. Structures in the dashboard presented a risk of injury to the knees and femurs of the driver and front passenger, and protection of that body region was rated as marginal. Good protection was provided in the side barrier test and the car scored maximum points. In the more severe side pole impact, readings from the dummy chest indicated a weak level of protection. Marginal protection was provided against whiplash injuries in the event of a rear impact.

Bambini

Forward movement of the 3 year dummy's head was not excessive in the frontal impact. In the side impact, the heads of both dummies were properly contained by their respective restraints. The passenger airbag can be disabled by Subaru dealers to allow a rearward facing child restraint to be used in that seating position. The dangers of doing so without first disabling the airbag are explained in a sun visor label which is permanently attached, but this label is not available in all European languages.

Pedoni

The bumper offered good protection to pedestrians' legs in most areas. The bonnet also performed well in most areas likely to be struck by the head of an adult or a child. However, the front edge of the bonnet scored no points for the protection it offered to pedestrians.

Dispositivi di sicurezza

Electronic stability control is standard equipment on the Legacy, as is a seatbelt reminder for the driver and front passenger seats.