




Ford S Max

[Immagini](#) | [Video](#)

VALUTAZIONI	PUNTEGGIO	
 ADULTI 	36	Anteriore: 15,8 Laterale: 16 Sistema SBR: 2 Pole test: 2
 BAMBINI 	39	
 PEDONI 	13	


Protezione dei passeggeri adulti



Sistema di ritenuta per bambino

Bambino di 18 mesi Britax-Römer BabySafe ISOFIX Plus, rearward facing
 Bambino di 3 anni Britax-Römer Duo Plus ISOFIX, forward facing

Protezione dei pedoni



Dotazione di sicurezza

Pretensionatori cinture di sicurezza anteriori	<input checked="" type="checkbox"/>
Limitatori di carico cinture di sicurezza anteriori	<input checked="" type="checkbox"/>
Airbag anteriore conducente	<input checked="" type="checkbox"/>
Airbag anteriore passeggero	<input checked="" type="checkbox"/>
Airbag laterali	<input checked="" type="checkbox"/>
Airbag laterale per la testa	<input checked="" type="checkbox"/>
Airbag ginocchia conducente	<input checked="" type="checkbox"/>

Dettagli della vettura testata

Modello testato	Ford S-MAX 'Trend', 2.0 diesel, LHD
Tipo carrozzeria	5 porte MPV
Anno di pubblicazione	2006
Peso	1743kg
Numero di identificazione veicolo (VIN) a cui si riferisce la valutazione	Applicabile a tutti veicoli Ford S-MAX

Vista anteriore ISOfix

Vista posteriore ISOfix

Commenti

Impatto frontale

The knee airbag protected the driver's knees and femurs from structures in the dashboard. The steering-wheel moved forward during the impact to provide greater protection for the driver. The chests of the driver and the passenger were the only body regions not to score maximum points.

Impatto laterale contro vettura

The S-MAX scored maximum points for its performance in the side impact and pole tests

Bambini

A passenger airbag deactivation switch can be bought as an option from Ford dealers. Euro NCAP has not assessed the switch or the information presented to the driver regarding the status of the passenger airbag. Without the switch, a rearward-facing child restraint should not be used in the front passenger's seat. The presence of ISOFIX anchorages in the second row outboard seats was not prominently marked.

Pedoni

The protection offered by the bumper to a pedestrian's leg was rated predominantly 'fair'. However, the leading edge of the bonnet scored no points for the protection offered to pedestrians' upper legs.