


Comparabile

Totale 28 punti | 78%



Totale 39 punti | 79%

	RESTAZIONI 10.4 punti	Bambino di 18 mesi Seggiolino Britax Romer Baby Safe ISOFIX Gruppo 0, 0+ Posizione All'indietro Installazione Ancoraggi ISOFIX e intelaiatura supporto
	RESTAZIONI 11.5 punti	Bambino di 3 anni Seggiolino Britax Romer Duo Plus Gruppo 1 Posizione In avanti Installazione Ancoraggi ISOFIX e punto d'aggancio

VALUTAZIONE BASATA SUL VEICOLO 5.0 punti

[Vedi commenti](#)

Totale 22 punti | 60%

	TESTA 10.4 punti	DISPOSITIVI DI LIMITAZIONE VELOCITÀ 0.0 punti
	BACINO 5.2 punti	CONTROLLO ELETTRONICO DELLA STABILITÀ (ESC) 3.0 punti
	GAMBA 6.0 punti	VSA
		SISTEMA SBR 2.0 punti
		conducente passeggero sedile posteriore

Legend:

- Buona (Green)
- Adeguata (Yellow)
- Marginale (Orange)

Dettagli della vettura testata

Specifiche

Modello testato

Honda Jazz 1.4 ES, LHD

Tipo carrozzeria

5 porte portello posteriore

Anno di pubblicazione

2009

Peso

1119kg

Numero di identificazione veicolo (VIN) a cui si riferisce la valutazione

Applicable a tutti applies new Jazz

Classe

SUPERMINI

Safety equipment

Pretensionatori della cintura di sicurezza sedile anteriore

Limitatori di carico cinture di sicurezza anteriori

Airbag anteriore conducente

a due fasi

Airbag anteriore passeggero

a una fase

Airbag laterali

Airbag laterale per la testa

Commenti

Protezione dei adulti

The passenger compartment remained stable in the frontal test. The driver's footwell was deformed but it did not rupture and retained its stability. Nevertheless, pedal displacements were high and that of the clutch incurred a penalty. Structures in the dashboard posed a hazard to the knees and femurs of the driver and passenger. In the side pole test, chest protection was poor, with rib deflections exceeding safe limits. However, protection of other body regions was good in both the side barrier and the pole tests. Protection against whiplash injury in rear impacts was rated as marginal.

Bambini

In the frontal test, forward head movement of the 3 year infant, sat in a forward-facing seat, was not excessive and both dummies' heads were contained by the restraints in the side impact. The passenger airbag can be disabled to allow a rearward-facing restraint to be used in that seating position. However, insufficient information is presented to the driver regarding the status of the airbag.

Pedoni

The bumper scored maximum points for the protection it offered to pedestrians' legs. The bonnet offered good protection in most areas where an adult's head might strike but was predominantly poor for protecting the heads of children.

Dispositivi di sicurezza

Honda is increasing the fitment of its electronic stability control (ESC) system during the course of 2009. Currently, ESC is fitted as an option to some variants in some countries, although the great majority of sales are expected to have ESC fitted as standard. Fitment will be increased until, by January 2010, ESC is standard equipment on all variants in all European countries. A seatbelt reminder system for the front and rear seats is standard equipment.