


Comparabile

Totale 21 punti | 58%



Totale 35 punti | 71%

RESTAZIONI	6.9 punti	Bambino di 18 mesi
ISTRUZIONI	4.0 punti	Seggiolino Britax Romer Baby Safe
INSTALLAZIONE	2.0 punti	Gruppo 0, 0+
		Posizione All'indietro
		Installazione Cintura di sicurezza per adulti
RESTAZIONI	8.8 punti	Bambino di 3 anni
ISTRUZIONI	4.0 punti	Seggiolino Britax Romer Duo Plus
INSTALLAZIONE	2.0 punti	Gruppo 1
		Posizione In avanti
		Installazione Ancoraggi ISOFIX

VALUTAZIONE BASATA SUL VEICOLO 7.0 punti

[Vedi commenti](#)

Totale 19 punti | 53%

TESTA	13.1 punti	DISPOSITIVI DI LIMITAZIONE VELOCITÀ	0.0 punti
BACINO	0.0 punti	CONTROLLO ELETTRONICO DELLA STABILITÀ (ESC)	3.0 punti
GAMBA	5.9 punti	VSC	
		SISTEMA SBR	3.0 punti
		conducente	
		passeggero	
		0	

Legend: Buona (Green), Adeguata (Yellow), Marginale (Orange).

Dettagli della vettura testata

Specifiche

Modello testato

Toyota Urban Cruiser 1.33 petrol, RHD

Tipo carrozzeria

5 porte MPV

Anno di pubblicazione

2009

Peso

1150kg

Numero di identificazione veicolo (VIN) a cui si riferisce la valutazione

from JTKKH16440J012088

Classe

PICCOLO MONOVOLUME

Safety equipment

Pretensionatori della cintura di sicurezza sedile anteriore

Limitatori di carico cinture di sicurezza anteriori

Airbag anteriore conducente

a una fase

Airbag anteriore passeggero

a una fase

Airbag laterali

Airbag laterale per la testa

Airbag ginocchia conducente

Commenti

Protezione dei adulti

The passenger compartment remained stable in the frontal impact. However, despite the presence of a knee airbag, the driver dummy's left knee made contact with the dashboard and recorded high values. Structures in the dashboard presented a risk of injury to the knees and femurs of both the driver and passenger. In the side pole test, the head curtain airbag failed to prevent a hard contact of the head. Although only the protection of the head was compromised, under such circumstances Euro NCAP does not award any points for this test as robust airbag performance is considered essential for predictable protection in real world accidents. Owing to the unintended airbag performance in the pole test, the same airbag was penalised in the side barrier test, reflected by a lowered score for the driver's head. Protection against whiplash injuries in a rear impact was rated as marginal.

Bambini

Forward movement of the head of the 3 year dummy was not excessive in the frontal impact (the 18 month dummy was sat in a rearward facing restraint). Both dummies were properly contained by the sell of their restraints in the side barrier impact. The passenger airbag can be deactivated to allow a rearward facing child restraint to be used in that seating position. Cars with serial numbers from JTKKH16440J012088 have a clearly marked switch and the system gives unambiguous information to the driver regarding the status of the airbag. The airbag cut-off switch of earlier cars is not so clearly marked and would not have received the 2 points awarded, although the car's overall star rating would be the same. Toyota have also recently updated the owner's handbook to make clear that, in those cases where the rear seat is adjustable, it should be set to its rearmost position when being used to transport children.

Pedoni

The front edge of the bonnet scored no points for the protection it offered to pedestrians' legs. However, the bumper offered good protection in most areas. The bonnet provided good protection in some areas likely to be struck by an adult's head or a child's, but was predominantly marginal or poor.

Dispositivi di sicurezza

The Urban Cruiser has electronic stability control as standard equipment on all variant throughout Europe A seatbelt reminder covering all seating positions is also standard.