


Comparabile



Totale 42 punti | 86%



RESTAZIONI	10.4 punti
ISTRUZIONI	4.0 punti
INSTALLAZIONE	2.0 punti

Bambino di 18 mesi

Seggiolino	Fair G0/1 ISOFIX
Gruppo	0, 0+
Posizione	All'indietro
Installazione	Ancoraggi ISOFIX e intelaiatura supporto



RESTAZIONI	11.9 punti
ISTRUZIONI	4.0 punti
INSTALLAZIONE	2.0 punti

Bambino di 3 anni

Seggiolino	Fair G0/1 ISOFIX
Gruppo	1
Posizione	In avanti
Installazione	Ancoraggi ISOFIX e intelaiatura supporto

VALUTAZIONE BASATA SUL VEICOLO 8.0 punti

[Vedi commenti](#)

Totale 18 punti | 49%

Totale 6 punti | 86%



TESTA	11.6 punti
BACINO	1.2 punti
GAMBA	4.9 punti



DISPOSITIVI DI LIMITAZIONE VELOCITÀ	0.0 punti
CONTROLLO ELETTRONICO DELLA STABILITÀ (ESC)	3.0 punti
ESC	
SISTEMA SBR	3.0 punti
conducente	
passeggero	
sedile posteriore	

Dettagli della vettura testata

Specifiche

Modello testato	Kia Sportage 2.0 diesel EX, LHD
Tipo carrozzeria	5 porte SUV
Anno di pubblicazione	2010
Peso	1625kg

Numero di identificazione veicolo (VIN) a cui si riferisce la valutazione

Applicabile a tutte le applies Sportages testate

Classe

PICCOLA FUORISTRADA 4x4

Safety equipment

Pretensionatori della cintura di sicurezza sedile anteriore

Limitatori di carico cinture di sicurezza anteriori

Airbag anteriore conducente

Airbag anteriore passeggero

Airbag laterali

Airbag laterale per la testa

Commenti

Protezione dei adulti

The passenger compartment remained stable in the frontal impact, the windscreen pillar being deformed rearward only 2mm after the test. Dummy readings showed good protection of the front passengers' knees and femurs. Kia was able to demonstrate that a similar level of protection would be offered to occupants of different sizes and to those sat in different positions. In the side barrier test, all body areas were well protected and the car scored maximum points. In the more severe side pole test, dummy readings of rib deflection indicated a marginal level of protection for the chest area. The seat and head restraint provided good protection against whiplash injuries in the event of a rear-end collision.

Bambini

In the frontal impact, movement of the 3 year dummy, sat in a forward facing restraint, was not excessive. In the side impact, both child dummies were properly contained within the protective shells of their restraints. The passenger airbag can be disabled to allow a rearward facing child restraint to be used in that seating position. The status of the airbag is clearly displayed to the driver, so that it is clear whether the seat is safe for a rearward facing restraint (airbag off) or for an adult passenger (airbag on). Kia recommend a different child restraint for universal installation using the adult seatbelts, and for installation using the ISOFIX anchorages. Owners should check their owner's manual for details and should ensure they have the restraint which is recommended for the intended method of installation.

Pedoni

The bumper provided good protection to pedestrians' legs in some of the areas tested but only marginal protection in others. The front edge of the bonnet provided predominantly poor protection. In most of the areas likely to be struck by a child's head, the bonnet offered good levels of protection. However, for an adult's head, most of the areas tested showed poor protection.

Dispositivi di sicurezza

Electronic stability control is fitted as standard on all variants. A seatbelt reminder system is standard for the front and rear seats.