


Comparabile

Totale 31 punti | 87%



IMPATTO FRONTALE

13.1 punti

IMPATTO LATERALE CONTRO VETTURA

7.5 punti

TAMPONAMENTO (COLPO DI FRUSTA)

3.3 punti

IMPATTO LATERALE CONTRO PALO

7.3 punti

Totale 42 punti | 86%



RESTAZIONI

12.0 punti

Bambino di 18 mesi

ISTRUZIONI

4.0 punti

Seggiolino Fair GO/1 ISOFIX

INSTALLAZIONE

2.0 punti

Gruppo 0, 0+

Posizione All'indietro

Installazione Ancoraggi ISOFIX e intelaiatura supporto



RESTAZIONI

12.0 punti

Bambino di 3 anni

ISTRUZIONI

4.0 punti

Seggiolino Fair GO/1 ISOFIX

INSTALLAZIONE

2.0 punti

Gruppo 1

Posizione In avanti

Installazione Ancoraggi ISOFIX e intelaiatura supporto

VALUTAZIONE BASATA SUL VEICOLO

6.0 punti

[Vedi commenti](#)

Totale 14 punti | 39%



TESTA

8.0 punti

DISPOSITIVI DI LIMITAZIONE VELOCITÀ

0.0 punti

BACINO

0.0 punti

CONTROLLO ELETTRONICO DELLA STABILITÀ (ESC)

3.0 punti

GAMBA

5.9 punti

ESP

3.0 punti



SISTEMA SBR

3.0 punti

conducente

passeggero

sedile posteriore

Dettagli della vettura testata

Specifiche

Modello testato

Kia Soul 1.6 EX, LHD

Tipo carrozzeria

5 porte portello posteriore

Anno di pubblicazione

2009

Peso

1170kg

Numero di identificazione veicolo (VIN) a cui si riferisce la valutazione

Classe

Applicable a tutti applies Kia Souls

PICCOLO MONOVOLUME

Safety equipment

Pretensionatori della cintura di sicurezza sedile anteriore

Limitatori di carico cinture di sicurezza anteriori

Airbag anteriore conducente

a una fase

Airbag anteriore passeggero

a una fase

Airbag laterali

Airbag laterale per la testa

Commenti

Protezione dei adulti

The passenger compartment remained stable in the frontal impact. Structures in the dashboard presented a risk of injury to the knees and femurs of the driver and passenger. Based on dummy readings alone, the Soul scored maximum points for its protection of the driver in the side barrier test. However, the driver's door was not fully latched after the test and the car was penalised a point. In the side pole test, protection of the chest was marginal. However, good protection was provided against whiplash injuries.

Bambini

Based on dummy readings, maximum points were scored for the protection provided to both the 3 year and the 1½ year children in the frontal and side impact tests. Forward movement of the head of the 3 year child, sat in a forward-facing seat, was not excessive in the frontal impact the heads of both dummies were contained by the restraints in the side impact. The passenger airbag can be disabled to allow a rearward-facing child restraint to be used in that seating position. However, information provided to the driver regarding the status of the airbag is not sufficiently clear.

Pedoni

The front edge of the bonnet offered poor protection to pedestrians' legs. In most areas likely to be hit by a pedestrian's head, the bonnet also provided poor protection. Only the bumper offered predominantly good protection against injury.

Dispositivi di sicurezza

Electronic stability control is standard equipment on all Kia Souls, as is a seatbelt reminder system for both front and rear seats.