



# Smart fortwo

[Immagini](#) | [Video](#)

## VALUTAZIONI



ADULTI



## PUNTEGGIO

28

Anteriore: 12,9  
Laterale: 14

Sistema SBR: 1



PEDONI



10

### Protezione dei passeggeri adulti



Conducente in impatto frontale



Passeggero in impatto frontale



Conducente in impatto laterale

<span style="background-color: green; border: 1px solid black; width: 10px; height: 10px;"></span>	Buona
<span style="background-color: yellow; border: 1px solid black; width: 10px; height: 10px;"></span>	Adeguata
<span style="background-color: orange; border: 1px solid black; width: 10px; height: 10px;"></span>	Marginale
<span style="background-color: brown; border: 1px solid black; width: 10px; height: 10px;"></span>	Scarsa
<span style="background-color: red; border: 1px solid black; width: 10px; height: 10px;"></span>	Insufficiente

### Sistema di ritenuta per bambino

Bambino di 18 mesi Not applicable

Bambino di 3 anni Not applicable

### Protezione dei pedoni



<span style="background-color: green; border: 1px solid black; width: 10px; height: 10px;"></span>	Buona
<span style="background-color: yellow; border: 1px solid black; width: 10px; height: 10px;"></span>	Adeguata
<span style="background-color: red; border: 1px solid black; width: 10px; height: 10px;"></span>	Marginale

Protezione dei pedoni

### Dotazione di sicurezza

Pretensionatori cinture di sicurezza anteriori

Limitatori di carico cinture di sicurezza anteriori

Airbag anteriore conducente

Airbag anteriore passeggero

Airbag laterali

Airbag laterale per la testa

Airbag ginocchia conducente

### Dettagli della vettura testata

Modello testato

smart fortwo,  
999cc "passion",  
LHD

Tipo carrozzeria

2 porte

Anno di pubblicazione

2007

Peso

750kg

Numero di identificazione  
veicolo (VIN) a cui si riferisce la  
valutazione

Applicabile a tutti  
fortwos

## **Commenti**

### **Impatto frontale**

The passenger cell remained stable during the impact. Structures in the dashboard presented a risk of injury to the knees and femurs of the driver and passenger.

### **Impatto laterale contro vettura**

The dummy's head contacted the rubber window trim on the cant rail, leading to a high deceleration. However, the data recorded by the dummy suggested an adequate level of head protection. A side impact airbag to protect the chest and the head is available as an option but was not fitted to the test vehicle.

### **Bambini**

There are no rear seats in the smart fortwo so child protection was not rated. An option package is available from smart which includes ISOFIX anchorages for the passenger seat and a switch to disable the passenger's side frontal airbag. The label warning of the dangers of fitting a rearward facing child restraint without first disabling the airbag was inadequate.

### **Pedoni**

The bumper scored maximum points for the protection it offered to pedestrians' legs. However, the front edge of the bonnet scored no points and those areas which might be struck by pedestrians' heads were rated as predominantly poor.