

TEST RESULTS

[Comparabile](#)

Opel/Vauxhall Adam

Opel Adam 1.4 JAM, LHD

TEST 2013



ADULTI



BAMBINI



PEDONI



SAFETY ASSIST




Totale 31 punti | 87%



Conducente Passeggero



Vettura Palo



	Buona
	Adeguata
	Marginale
	Scarsa
	Insufficiente

IMPATTO FRONTALE

14.5 punti

IMPATTO LATERALE CONTRO VETTURA

7.9 punti

TAMPONAMENTO (COLPO DI FRUSTA)

2.5 punti

IMPATTO LATERALE CONTRO PALO

6.6 punti

Totale 35 punti | 72%

CRASH TEST PERFORMANCE

20.9 punti

CHILD SAFETY FEATURES

5.0 punti

Bambino di 18 mesi (11.2 punti)



Seggiolino testato (attacco)
FAIR G0/1 (ISOFIX)

Forward facing



Attacco Isofix

Bambino di 3 anni (9.7 punti)



Seggiolino testato (attacco)
Römer Duo Plus (ISOFIX)

Forward facing

CRS INSTALLATION CHECK

9.5 punti

Neonati fino a 13 kg

Maxi Cosi Cabriofix (Seatbelt)

Maxi Cosi Cabriofix (Seatbelt)

Maxi Cosi Cabriofix and EasyFix (Seatbelt)

Maxi Cosi Cabriofix and EasyFix (ISOFIX)

Neonati e bambini fino a 18 kg

BeSafe iZi Kid X3 ISOfix (ISOFIX)

FAIR GO/1 (ISOFIX)

Bambini da 9 a 18 kg

Römer King Plus (Seatbelt)

Römer Duo Plus (ISOFIX)

Maxi Cosi Pearl and Familyfix (ISOFIX)

Bambini da 15 kg in su

Römer KidFix (Seatbelt)

Römer KidFix (ISOFIX)



Installazione senza
problemi

Installazione accurata

Problema per la sicurezza

Installazione non
consentita

Totale 24 punti | 65%



TESTA

13.6 punti

BACINO

4.0 punti

GAMBA

6.0 punti

GOOD

ADEQUATE

MARGINAL

WEAK

POOR

Totale 7 punti | 81%

SISTEMA SBR

driver and passenger
sedile posteriore

3.0 punti

Approvato
Approvato

CONTROLLO ELETTRONICO DELLA STABILITÀ (ESC)

ESC

3.0 punti

Approvato

DISPOSITIVI DI LIMITAZIONE VELOCITÀ

Di serie
Speed Information
Speed Assistance (Manual)

1.3 punti

Non valutato
Approvato

Dettagli della vettura testata

Specifiche

Modello testato

Opel Adam 1.4 JAM, LHD

Tipo carrozzeria

3 porte portello posteriore

Anno di pubblicazione

2013

Peso

1067kg

**Numero di identificazione veicolo (VIN) a cui si
riferisce la valutazione**

from WOLOMAP08E6000067

Classe

Supermini.

Safety equipment

Pretensionatori della cintura di sicurezza sedile

anteriore**Limitatori di carico cinture di sicurezza anteriori****Airbag anteriore conducente****Airbag anteriore passeggero****Airbag laterali****Airbag laterale per la testa****Dispositivi di limitazione velocità****Controllo elettronico della stabilità****Segnalazione di cintura di sicurezza non allacciata** Driver, Passenger and Rear

Commenti

Protezione dei adulti

The passenger compartment of the Adam remained stable in the frontal impact. Dummy readings indicated good protection of the knees and femurs of the driver and passenger. Opel showed that a similar level of protection would be provided for occupants of different sizes and to those sat in different positions. The car scored maximum points for its protection of the passenger dummy, with all body areas being well protected. In the side barrier test, the Adam demonstrated good protection of all body regions except the chest, which was adequately protected. In the more severe side pole test, dummy readings of rib deflection indicated weak protection of the chest, although other parts of the body were well protected. The seat and head restraint provided marginal protection against whiplash injury in the event of a rear-end collision.

Bambini

In the frontal impact, forward movement of the child dummies, both sat in forward-facing restraints, was not excessive but protection of their chests was rated as fair owing to the chest decelerations measured. In the side impact, both dummies were properly contained by their restraints, minimising the likelihood of dangerous head contact with parts of the car interior. The passenger airbag can be disabled to allow a rearward-facing child restraint to be used in that seating position. Clear information is provided to the driver about the status of the airbag and the system was rewarded. The rear outboard seats could not accommodate the group II/III child restraint but, otherwise, all restraints for which the car was designed could be accommodated without a problem. Cars before VIN WOL0MAP08E6000067 contain slightly different information in the user manual regarding installation of the group II/III restraint in the front passenger seat.

Pedoni

The bumper scored maximum points for the protection it provided to pedestrians' legs. The front edge of the bonnet was good in most areas tested but provided poor protection at the outer edges. The bonnet surface, where a child's head might strike, showed mixed performance with areas of good, adequate and marginal protection. The windscreens offered good head protection to taller pedestrians but was poor around the windscreens pillars and at the base of the screen.

Dispositivi di sicurezza

Electronic stability control is standard on the Adam and passed Euro NCAP's test requirements. A seatbelt reminder system covers the front and rear seats and a driver-set speed limitation device met Euro NCAP's requirements for such systems.